## Annexure D

## **BUILDING SAFETY CERTIFICATE**

No.

Dated: 17.02.2024

It is certified that the existing building of Mount Carmel School (name of the building or premises) at Sector 47-B, Chandigarh, is having Block(s) as per details below:

Detail of Block(s) in	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
School	A	8	C			
No. of	354004	356004	2 5-6000	1	1	1
Floor(s) in the	GF, FP, SE	GF, FF, SF	GF, FF	,		,
Block	Basement	120sement	Bosement.			

The building is owned/occupied by Mount Carmel School, have complied with the Building Safety requirements in accordance with National Building Code Rules, and verified by the officers concerned of Er. SHIV DEV SINGH (Name of Department/ Govt.) on 16.02, 2024...(date of inspection) in the presence of Dr. Annie Charles Samuel, Secretary, Mount Carmel Educational Society (name and addresses of the Manager/Secretary or his representative) and that the Building/Premises is fit for occupancy for running School with effect from Feb. 2024... for a period of conditions as appended.

13	100I	-
in	I. SCH	digar
ietz	IRME	Снаг
REER	NIC	r 17-R
93	TOL	poton

1. Confficate affa	1.	Chea
--------------------	----	------

Issued on 17.02.2024 at Chandy L by Er SMIN DEN SINGH

\* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal:

DEV SINGH PE (USA), MIE(I) FIIA,

Name & SAIN DEN SINGH

NO. M-019103-5 ENGIN No. 3255, Sector 35-D

Designation: Eugmoer

Chandigarh (UT) 160022. India

Dr. Parveena John Singh Principal Mount Carmel School Chandigarh

Name & Address of Department/ Office: M. 3255 SECTOR 35-D, CHD. (UT)

## S. D. SINGH & ASSOCIATES


ARCHITECT. CHARTERED ENGINEERS, VALUERS SURVEYOR/LOSS ASSESSORS (GOVT. OF INDIA)
# 3255, SECTOR 35-D, CHANDIGARH-160022 - INDIA, Ph.: 0172-2620536

Ref. No.

ARCHITECT STRUCTURAL ENGINEERS, REGISTERED VALUERS SPACE PLANNERS, INTERIOR DECORATORS, CONTRACTORS, SURVEYOR/LOSS ASSESSORS, PERSONNEL & MANAGEMENT CONSULTANTS

Date ..17:02:2024

## TO WHOM IT MAY CONCERN



- b) In case of any addition/alteration/expansion/modification this building is to be accured, the same be carried out under the supervision of a qualified engineer and this certificate may again be obtained from the undersigned after the completion.
- c) In case the building is affected by the floods or if there is any settlement of walls/foundations or sagging of roofs etc immediate inspection of the undersigned be arranged to check the stability and safety of the building.
- d) The building can be safely occupied for normal use.
- e) The Certificate is valid for 3 years.

SHIV DEV SINGH
ME, PE (USA), MIE(I) FIIA, FIV
STRUCTURAL ENGINEER
No. M-019103-5 ENGINEER
No. 3255, Sector 35-D
Chandigarh (UT) 160022. India

Er. Shiv Dev Singh Regd. Structure Engineer Chd. (UT) Dr. Parveena John Singh Principal Mount Carmel School Chandigarh

GLOBAL FOUNDATION
Ar. S.D.SINGH

ARCHITECT STRUCTURAL ENGINEER B.E. B.COM, M.E.P.E. (USA). MIE(I), FIV FIIA MCA, ASSOCIATE-AIA Mob.: 9872894879

Email: sdsingharchitect@gmail.com

Ar. ANJU BALA
ARCHITECT
AIIA-MCA
Mob.: 9915132359

Email: anjubalaarchitect@yahoo.com

MANAGER
MOUNT CARMEL SCHOOL
Sector 47-B, Chandigarh